

Size	Across The Flats	Height	Thread Depth
1/4	.430	.460	.361
5/16	.510	.520	.460
3/8	.550	.620	.560
1/2	.750	.800	.660
5/8	.940	.980	.770
3/4	1.067	1.146	.930